

Measure no.

US 53528266-03

Subject

Fault code memory entry 0x21F960, throttle valve

Status date (mm/dd/yy)

10/31/14

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

10/31/14

Created by

Rainer Wanninger

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K48

Engine

6-ZYL

Body**Production period (from/to)**

(mm/dd/yy)

8/31/10 / 3/11/12

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

Complaint

Engine warning light lights up when the vehicle is in motion. Fault 0x21F960 throttle valve 1

"Comparison fault adapted values" is stored in the fault code memory.

Cause

Software error

Measure

Program the Digital Engine Electronics (DME) to the most recent software status

Complaint

Fault location	Fault type	Fault place
Engine running	Engine: Dying off	

Cause

#	Fault location	Fault type	Fault place
1	13/61 DME engine control unit	Software error	
	Repair Task	Special Clearance	Area
	Program/encode	No	Powertrain

Fault code

Progman / DIS / ISTA / ISTA/P

System

State

Version

© 2002-2014 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.