

## Clock is slow in vehicles without navigation

---

Topic number	LI54.30-P-066875
Version	2
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	08-28-2017
Validity	BR205/BR253 without navigation (without code 355).
Reason for change	Cause adjusted.
Reason for block	

---

### Complaint:

In vehicles without navigation, the clock is slow and falls behind (by approx. 5-10 minutes per month).

### Cause:

Under analysis, no further cases are needed at this time.

### Remedy:

Do not replace any parts at this time.

<b>Symptoms</b>
Communication/information / Information display / Displays / Clock / Too slow