

# Latest Vehicle Concern Fixes



Recovery Panel Fitment	XCL
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>Customers may report the removable recovery panel is loose incorrectly aligned.</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>The recovery panel (front or rear) may not have been installed correctly at PDI or there is a quality concern preventing proper installation.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>Engineering is currently investigating installation concerns regarding recovery cover panels.</li><li>Should any issues be encountered during installation or a customer's vehicle return with a recovery cover panel concern, please submit an EPQR detailing the issue with pictures of the panel and vehicle mounting locations.</li></ul>	

