

## Latest Vehicle Concern Fixes



Wheel Arch Liner Contacting Front Stabilizer Bar	Discovery Sport 15MY - Onwards
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>A customer may report a noise from the front suspension while driving over speed bumps or rough road surfaces.</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>This may be caused by a front wheel arch liner center section that has become incorrectly positioned from high speed driving and contacts the front stabilizer bar.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>TSB LTB01285 is being published to address this concern by modifying the front wheel arch liner center section.</li><li>Should a customer express a concern, please refer to this TSB for repair instructions.</li></ul>	

