

## ESM (electronic selector lever module) fault 0002 "Undervoltage"

---

Topic number	LI27.60-N-048766
Version	4
Design group	27.60 Gearshift, control
Date	06-12-2017
Validity	Sprinter model designation 906 with code G40
Reason for change	Distribution revised
Reason for block	

---

### Complaint:

The vehicle enters reduced-propulsion mode and has stored the fault 0002 'Undervoltage' in the ESM control unit.

### Cause:

Fault 0002 'Undervoltage' in the ESM control unit will place the vehicle into "reduced-propulsion mode"

### Remedy:

Check possible reasons and remedies, as described in the DAS, and process where applicable.

Load new software for the ESM control unit.

<b>Symptoms</b>
Power transmission / Automatic transmission / Function / Limp-home mode

<b>Parts</b>						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 906 260 35 09			ESM shift mechanism	1	For LHD vehicles: Observe the note in the EPC!	X

<b>WIS-References</b>			
Document number	Title	Note	Allocation
AR27.60-D-0901B	Remove/install electronic selector lever module (ESM)	Only replace the ESM if flashing was unsuccessful!	Remedy