

Indicator lamps for brake system light up

Topic number	LI42.45-N-048724
Version	2
Design group	42.45 Electronic stability program (ESP)
Date	06-21-2017
Validity	Sprinter model designation 906.###
Reason for change	Distribution revised
Reason for block	

Complaint:

Indicator lamps for brake system light up.

ESP not functioning.

Cause:

Road test for ESP active. Fault code 4E51.

Remedy:

The road test must be performed again!

The road test consists of two phases:

1. Stationary.
2. Driving.

During the 1st phase, while stationary, the "ASR OFF" switch should be operated after depressing the brake pedal, and then follow the instructions in DAS.

Symptoms
Chassis/suspension / Brake system / Brakes/traction regulation system / Electronic Stability Program ESP / Indicator lamp / lit

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			43181 73	Traction system control unit – electrical fault The listed damage code is not to be considered as an acceptance of costs. The general guidelines in the Warranty Manual apply.

XENTRY TIPS

Validity		
Vehicle	Engine	Transmission
Sprinter III - 906.111	*	*
Sprinter III - 906.113	*	*
Sprinter III - 906.131	*	*
Sprinter III - 906.132	*	*
Sprinter III - 906.133	*	*
Sprinter III - 906.134	*	*
Sprinter III - 906.135	*	*
Sprinter III - 906.136	*	*
Sprinter III - 906.153	*	*
Sprinter III - 906.155	*	*
Sprinter III - 906.211	*	*
Sprinter III - 906.213	*	*
Sprinter III - 906.231	*	*
Sprinter III - 906.233	*	*
Sprinter III - 906.235	*	*
Sprinter III - 906.253	*	*
Sprinter III - 906.255	*	*
Sprinter III - 906.611	*	*
Sprinter III - 906.613	*	*
Sprinter III - 906.631	*	*
Sprinter III - 906.633	*	*
Sprinter III - 906.635	*	*
Sprinter III - 906.637	*	*
Sprinter III - 906.653	*	*
Sprinter III - 906.655	*	*
Sprinter III - 906.657	*	*
Sprinter III - 906.711	*	*
Sprinter III - 906.713	*	*
Sprinter III - 906.731	*	*
Sprinter III - 906.733	*	*
Sprinter III - 906.735	*	*