

## LED light on thermal cup holder in rear passenger compartment of BR 222 flickers

---

Topic number	LI82.20-P-067107
Version	1
Function group	82.20 Interior lights
Date	10-05-2017
Validity	MY2018 BR222 with code 224 & 877/ 891
Reason for change	
Reason for block	

---

### Complaint:

Intermittent flickering of the white ambient LED lighting on thermal cup holder in rear passenger compartment of BR 222. The blue and red ambient lights are not affected. Particularly when additional consumers are switched on, e.g. the massage function in the rear seat.

### Cause:

Possible additional consumer power usage

### Remedy:

Please create a PTSS case, guidance will be provided in the case.

<b>Symptoms</b>
Overall vehicle / Lighting / Interior illumination / Stowage compartment lighting / Flickers

<b>Validity</b>		
Vehicle	Engine	Transmission
S (222)	*	*