

Lever for seat height adjustment worn

Topic number	LI91.10-P-067199
Version	1
Function group	91.10 Front seats
Date	10-20-2017
Validity	Model designation 176.052, 117.352, 117.952, 156.952
Reason for change	Error in RP object number
Reason for block	

Complaint:

The lever for the seat height adjustment can rub on the seat, so increased wear between the lever and the seat is possible.

Cause:

Slider on lever for seat height adjustment to prevent friction is missing (see attachment).

Remedy:

Replace lever for seat height adjustment.

Symptoms
Body / Seat / Seat adjustment / Stiff/sluggish

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 246 910 05 02			Height adjustment lever	1	Left seat (footnote (ES2) as per EPC)	X
A 246 910 06 02			Height adjustment lever	1	Right seat (footnote (ES2) as per EPC)	X

Attachments	
File	Description
Hebel_Sitzhöhenverstellung.JPG	Lever with slider (anti-friction cover)

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			91A19 **	Left front seat height adjustment lever

XENTRY TIPS

			91N19 **	Right front seat height adjustment lever
--	--	--	----------	--

Attachments

Hebel_Sitzhöhenverstellung.JPG:

