

Parts of ambient lighting fail

Topic number	LI82.20-P-067044
Version	2
Function group	82.20 Interior lights
Date	10-25-2017
Validity	BR 213 code 808, 222 facelift and 238
Reason for change	Traces and videos no longer required
Reason for block	

Complaint:

Operational complaints of ambient lighting and no fault codes are logged in the ambient lighting control unit.

Cause:

Software error

Remedy:

IMPORTANT: The LEDs communicate over the LIN bus and are controlled via the ambient lighting control unit. The head unit is only for making settings. Therefore, replacing the head unit and wiring harnesses does not remedy the complaint.

New software is expected to be available in December. This TIPS document will be updated as soon as the software is available in the field.

Symptoms
Overall vehicle / Lighting / Interior illumination / Ambiance illumination / Does not go on