


LATEST VEHICLE CONCERN FIXES



Automatic Emergency Braking Not Available in Instrument Pack	18MY – 19MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport
<p>Customer Voice:</p> <ul style="list-style-type: none">– Automatic Emergency Braking not available– Forward alert not available.– Emergency Lane Keeping not available. <p>Technical Description:</p> <ul style="list-style-type: none">– Automatic Emergency Braking not available– Forward alert not available.– Emergency Lane Keeping not available. <p>Status:</p> <ul style="list-style-type: none">– Permanent Corrective Action by the supplier is planned for beginning of April.– Report any known cases via EPQR.	 <p>The image shows a close-up of a vehicle's instrument cluster. At the top, it displays '0 mph' and '69°F'. Below the speedometer, there is a large yellow 'i' in a circle, indicating an information or warning message. The text on the screen reads: 'OK to drive with caution Autonomous Emergency Braking not available'. At the bottom, it says 'Press OK to clear'. There are also icons for 'PARK', '3:24 PM', and '7%' fuel level.</p>

