

LATEST VEHICLE CONCERN FIXES



Knocking Noise When Driving Over Bumps	I-PACE 19 MY
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">– Customer may report a knocking noise when driving over bumps. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">– A knocking noise may be heard from the front suspension when driving over bumps at speeds between 13 km/h (8 mph) and 32 km/h (20 mph).– This may be caused by the front left and/or right shock absorber rebound spring making contact with its stop position. <p><u>Status:</u></p> <ul style="list-style-type: none">– JTB00674NAS2 to be updated to include an end VIN	

