

LATEST VEHICLE CONCERN FIXES



Incorrect Function of Climate Seat Control From Touchscreen	I-PACE 19 MY
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- A Customer may report the climate seat function may turn ON and then OFF <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- On vehicles with climate seats only, the climate seat function may turn ON and then OFF after selecting the seat squab icon on the Touchscreen. <p><u>Status:</u></p> <ul style="list-style-type: none">- JTB00681NAS2 to be released with additional steps if the vehicle displays a 'Brake Pedal Reduced Feeling' warning message on the Instrument Cluster after the CCF update.	

