

TECHNICAL NEWS 194 REMINDER



Notice Information

Ref	10165
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CAN) – March 12, 2019

TOL Ref. # 10165-SVC

Technical News 194 Reminder

As a reminder to dealers, Technical News 194 is now available for download on the Triumph Technical News library located at **Triumph Online > Service/Technical > Technical News** or you can consult the attached **Technical News 194 PDF**. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

Contents		
Item	Subject Model Affected	Model Affected
194.1	Front Master Cylinder Reservoir Cap Screws	Street Triple S, Street Triple S 35kw, Street Triple S 660cc
194.2	Windscreen Support Fixings Tiger	Tiger 800 XR, Tiger 800 XRX, Tiger XRX - LRH, Tiger 800 XCX, Tiger 800 XRT and Tiger 800 XCA
194.3	Keyless Ignition	Speed Triple RS, Tiger 1200 XRX, Tiger 1200 XRXLRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA, Scrambler 1200 XC, Scrambler 1200 XE
194.4	Clutch Cover Removal and Installation	Tiger 800 XR, Tiger 800 XRX, Tiger 800 XCX, Tiger 800 XRT and Tiger 800 XCA, Tiger 800 XRX-LRH
194.5	Rider's Seat (single seat)	Thrupton 1200, Thrupton 1200R
194.6	Side Stand Spring Peg	Street Cup, Street Twin, Bonneville T100 models from VIN 759204, Street Scrambler, Thrupton 1200, Thrupton 1200R, Bonneville T120 models
194.7	Cylinder Head Installation	Tiger XCX, Tiger 800 XR, Tiger 800 XRT, Tiger XRX, Tiger XRX - LRH and Tiger 800 XCA
194.8	Alternator Oil Feed Spray Jet	Speed Triple 1050 from VIN 735438 to VIN 846800, Speed Triple 1050R from VIN 735337 to VIN 858022, Speed Triple S from VIN 867685, Speed Triple RS from VIN 867601
194.9	Headlight and Indicator Wiring Harness Routing	Bonneville Bobber, Bonneville Bobber Black, Bonneville Speedmaster
194.10	Transmission Output Shaft	Tiger Explorer, Tiger Explorer XC, Tiger Explorer XC

		(from VIN 740277), Tiger Explorer XCA, Tiger Explorer XCX, Tiger Explorer XR, Tiger Explorer XRA, Tiger Explorer XRT, Tiger Explorer RX, Tiger 1200 XR, Tiger 1200 XRX, Tiger 1200 XRX-LRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA
194.11	Horn Wire Routing	Street Triple RS from VIN 800262, Street Triple S from VIN 803572, Street Triple R from VIN 806646, Street Triple R - LRH from VIN 822626 and Street Triple S 660 cc from VIN 800262
194.12	Instrument Downloads - 900cc and 1200cc Modern Classic Models with Analogue/LCD Instruments	Bonneville T100 from VIN 759204, Bonneville T120, Bonneville Bobber, Bonneville Bobber Black, Bonneville Speedmaster, Speed Twin, Street Cup, Street Scrambler, Street Twin, Thruxton from VIN 743684, Thruxton R
194.13	Pinpoint Test - Engine Start/Stop Switch Correlation Error	Tiger 1200 XRX, Tiger 1200 XRX-LRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA
194.14	Diagnostic Trouble Code (DTC) P2138 - Twist Grip Position Sensor 1 Correlation Error with Twist Grip Position Sensor 2	All models with ride by wire throttle
194.15	Electronic Systems Commissioning and Motorcycle Unlocking	Scrambler 1200 XC, Scrambler 1200 XE
194.16	Battery Anti-Tamper Label	All models

If you have any questions, contact your Regional Manager or call Triumph Customer Support at (888) 284-6288.