

## LATEST VEHICLE CONCERN FIXES



### BCCM Setting U3000-49

### 19MY I-PACE

#### Customer Voice:

- Vehicle will not charge

#### Technical Description:

- The charge indicator light will flash white, indicating the vehicle will not charge and is in the initializing phase. U3000-49 is stored in the BCCM

#### Status:

- Under Investigation
- In many cases, the U3000-49 code will prevent the BCCM from being programmed. Please raise a TA and follow LTS guidance.
- Should the BCCM ultimately need to be replaced, retain the parts and raise and provide your parts manager mailing information in either the TA or in an EPQR.

