



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-301

Date: September, 2017

INFORMATION

Subject: Information on DTC P2598 - Turbocharger Vane Position Performance Low Position

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Cruze	2017	2018			Diesel (RPO LH7)	
Chevrolet	Equinox	2018	2018				
GMC	Terrain	2018	2018				

Involved Region or Country	North America
Condition	The technician may find DTC P2598 set or stored while performing PDI.
Cause	This condition may be caused by lack of vacuum to the turbo actuator while the EGR bypass is being actuated. This is due to busy, braking maneuvers, between the assembly plant and the dealers.
Information	If you encounter a vehicle with the above condition, clear the DTC. Do not make any repair attempts.

Parts Information

No parts are required for this repair.

Version	1
Modified	Released September 20, 2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION