



# Technical Service Bulletin

SUBJECT:		No: <b>TSB-19-42A-003</b>	
<b>TORQUE UPDATES TO LIFTGATE REMOVAL &amp; INSTALLATION PROCEDURE - SERVICE MANUAL REVISION</b>		DATE: <b>April 2019</b>	
		MODEL: <b>2011-17 Outlander Sport/RVR</b>	
<b>CIRCULATE TO:</b>	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER

## PURPOSE

This TSB updates the Body section of the affected Service Manual, to correct the tightening torque for the liftgate removal and installation procedure, and to correct a non-reusable part indicator.

## AFFECTED VEHICLES

- 2011 - 2017 Outlander Sport/RVR

## AFFECTED SERVICE MANUAL

- 2011 - 2017 Outlander Sport/RVR Service Manual, Group 42-Body



Please make the indicated changes to the 2011 - 2017 Outlander Sport Service Manual, Group 42-Body -> Liftgate -> Removal and Installation.

