

Technical Service Bulletin

SUBJECT:			No:	TSB-19-34-003
UPDATE TO SHOCK ABSORBER ASSEMBLY			DATE:	April 2019
INSTALLATION - SMR			MODEL:	See below
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER		[X] TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[] WARRANTY PROCESSOR		[] SALES MANAGER

PURPOSE

This TSB updates the Rear Suspension section of the affected Service Manuals to delete the requirement for an installation direction of the coil spring end of the shock absorber assembly.

The installation direction of the coil spring end is not important when installing the shock absorber assembly (LH and RH).

AFFECTED VEHICLES

- 2009 2015 Lancer
- 2011 2015 Lancer Sportback
- 2014 2015 Outlander
- 2011 2015 Outlander Sport/RVR

AFFECTED SERVICE MANUALS

- 2009 2015 Lancer, Service Manual, Group 34-Rear Suspension
- 2011 2015 Lancer Sportback, Service Manual, Group 34-Rear Suspension
- 2014 2015 Outlander, Service Manual, Group 34-Rear Suspension
- 2011 2015 Outlander Sport/RVR, Service Manual, Group 34-Rear Suspension



Please make the indicated changes to the Service Manuals listed below, Group 34-Rear Suspension -> Shock Absorber Assembly -> Removal and Installation -> Installation Service Point.

- 2009 2015 Lancer
- 2011 2015 Lancer Sportback
- 2014 2015 Outlander
- 2011 2015 Outlander Sport/RVR

