

# LATEST VEHICLE CONCERN FIXES



Engine Vibration	F-PACE / Velar 2018 MY Onwards
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>- A customer may express a concern that vibrations can be felt from within the passenger compartment</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>- 2.0L Diesel Engine Vibration Caused By The Engine Mount Splitting and/or Leaking</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>- LTB01287 &amp; JTB00685 Published to replace the active engine mounts</li></ul>	

