Subject: Engineering Information – Reduced Engine Power, DTC P0299 Set

This PI has been revised to update the information with direction for further diagnosis. Please discard PIE0503A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore	2015	2019			Equipped with 1.4L Engine (RPO LUV)	Equipped with TRANSMISSION -AUTO 6 SPD, TRANSMISSION -MAN 6 SPD (RPOs MNK, MR5)
Cadillac	XT4	2019				Equipped with 2.0L Engine (RPO LSY)	Equipped with TRANSMISSION -AUTO 9 SPD (RPO M3H)
Chevrolet	Sonic	2015				Equipped with 1.4L Engine	TRANSMISSION -AUTO 6 SPD,
	Trax					(RPO LUV)	-AOTO 6 SPD, TRANSMISSION -MAN 6 SPD (RPOs MNK, MR5)
	Equinox	2018				Equipped with 1.5L, 2.0L Engines (RPOs LYX, LTG)	Equipped with TRANSMISSION -AUTO 9 SPD (RPOs M3H, M3D)
	Silverado 1500 (New Model)	2019				Equipped with 2.7L Engine (RPO L3B)	Equipped with TRANSMISSION -AUTO 8 SPD (RPO MQE)
GMC	Terrain	2018				Equipped with 1.5L, 2.0L Engines (RPOs LYX, LTG)	Equipped with TRANSMISSION -AUTO 9 SPD (RPOs M3H, M3D)
	Sierra 1500 (New Model)	2019				Equipped with 2.7L Engine (RPO L3B)	Equipped with TRANSMISSION -AUTO 8 SPD (RPO MQE)

For 2016–2019 Buick Envision, 2018–2019 Chevrolet Equinox and 2018–2019 GMC Terrain, refer to Bulletin 18-NA-020 for further diagnosis. For all other vehicles, refer to SI for further diagnosis.

Version	3

Modified	Revised February 20, 2019 – Ended the need for information from the field.
	Revised March 29, 2019 – Updated the information with direction for further diagnosis.