
Reference	SSM74329
Models	Discovery / L462 Range Rover / L405 Range Rover Sport / L494 Range Rover Velar / L560
Title	Suspension Air Supply Unit Expansion Chamber - Renew
Category	Chassis
Last modified	15-Apr-2019 00:00:00
Symptom	304000 Suspension System
Content	<p>Issue: Air suspension compressor being replaced for an E Chamber failure.</p> <p>Cause: Lower level repair not released across all models.</p> <p>Action: Please note that when there is a failure of the E Chamber unit, a lower level repair process is available in Topix.</p> <p>The relevant RTS code in Topix is 60.50.49</p> <p>In the event of suspected compressor failure, please check the E Chamber is not the root cause. If it is determined that it is, follow the lower level process as mentioned above.</p> <p>Warranty claims for this issue will be closely monitored going forward.</p>