

LATEST VEHICLE CONCERN FIXES



GTDi Camshaft Bearing Wear	14-17 MY Discovery Sport and RR Evoque
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- The vehicle will not start.- The Check Engine Light is on, there is noise from the engine. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- Wear is noted on the camshaft bearing surfaces. <p><u>Status:</u></p> <ul style="list-style-type: none">- We are working to better understand all contributing factors to this damage.- Ensure proper maintenance has been carried out on any vehicle exhibiting this condition. Inspect the oil and oil filter for contamination to assist in determining correct level repair.- Raise an EPQR which includes pictures of the damage, a picture of an oil sample, and maintenance records for the vehicles.	

