



Bulletin No.: PIP5423b
Published date: N/A

Preliminary Information

PIP5423b SES Lamp Setting A P0106 And/Or P0506

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CTS-V	2015 - 2019	All	All	6.2 LT4	All
Cadillac	Escalade	2015 - 2019	All	All	6.2 L86	All
Chevrolet	Camaro	2016 - 2019	All	All	6.2 LT1 LT4	All
Chevrolet	Corvette	2014 - 2019	All	All	6.2 LT1 LT4 LT5	All
Chevrolet	Silverado LD	2014 - 2019	All	All	4.3 5.3 6.2 L83 L86 LV3	All
Chevrolet	Silverado 1500 (New Model LD	2019	All	All	4.3 5.3 6.2 L82 L84 L87 LV3	All
Chevrolet	Suburban	2015 - 2019	All	All	5.3 6.2 L83 L86	All
Chevrolet	Tahoe	2015 - 2019	All	All	5.3 6.2 L83 L86	All
GMC	Sierra Limited	2014 - 2019	All	All	4.3 5.3 6.2 L83 L86 LV3	All
GMC	Sierra 1500 (New Model)	2019	All	All	4.3 5.3 6.2 L82 L84 L87 LV3	All
GMC	Yukon	2015 - 2019	All	All	5.3 6.2 L83 L86	All

Involved Region or Country:	North America
Condition:	A vehicle may have a concern of the SES lamp with a P0106 and P0506
Cause:	This maybe caused by a broken valve spring

Correction:

Replace the broken valve spring if the valve did not drop and cause block damage

Service Procedure:

Remove the valve cover and inspect for a broken valve spring.

If a broken valve spring is found inspect the intake manifold for a collapsed runner.

Version History

Version	2
Modified	09/27/2016 - Created 04/08/2019 - Updated to add Model year and RPO codes. 4/09/2019 - Updated Modle Years and Engine RPOs



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.