

Preliminary Information

PIC6042B Diagnostic Tip - Replacement of Manual Shift Paddles on Steering Wheel

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to	Engine.	Transmissions.
Cadillac	ATS	2013 - 2019	ALL	ALL	ALL	ALL
Cadillac	CTS VIN D	2009 - 2015	ALL	ALL	ALL	ALL
Cadillac	CTS Sedan VIN A	2014 - 2019	ALL	ALL	ALL	ALL
Cadillac	хтѕ	2013 - 2019	ALL	ALL	ALL	ALL

Supersession Statement

This PI has been update to add model years, please discard PIC6042A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

A Manual Shift Auxiliary Position Switch (Shift Paddle) may need to be replaced for any number of reasons.

Recommendations / Instructions

If replacement of either shift paddle is necessary, the steering wheel does NOT need to be replaced nor does it need to be removed to replace either shift paddle.

Please refer to Service Information "Manual Shift Auxiliary Position Switch Replacement -Steering Wheel" for the applicable vehicle you are working on for the replacement procedure.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.