

SSM 47971 - 2019 Fusion, 2018-2019 MKZ - 2.0L - Auto Start/Stop - No Auto Restart After An Auto Stop Event With DTC P164C

Some 2019 Fusion, 2018-2019 MKZ vehicles equipped with a 2.0L engine may exhibit an auto start/stop, no auto restart concern with diagnostic trouble code (DTC)P164C. A revised crankshaft position (CKP) sensor JX6Z-6C315-B is available. Refer to the Workshop Manual (WSM), Section 303-14B for Fusion and Section 303-14Afor MKZ. For claiming, use causal part 6C315 and applicable labor operations inSection 10 of the Service Labor Time Standards (SLTS) Manual.