

May 10, 2019

Version 2

TSX Passenger's Front Airbag Inflator Inspection

This bulletin is cancelled because the inspection is complete.

If you completed the repair described by this service bulletin on or before May 10, 2019, make sure to use the Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Failed Part Number
7540A6	TSX - Inspect the original airbag inflator installation.	0.3 hr	Z0400	V2W00	77820-TL2-A20
7541G1	TSX - Inspect the inflator and replace the original airbag module.	0.5 hr	Z0400	V2W00	77820-TL2-A20

Skill Level: Repair Technician

END

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.