


LATEST VEHICLE CONCERN FIXES



NLI – Bluetooth connectivity concerns with Android equipped device	15MY – 19MY E-Pace, F-PACE, F-TYPE, XE, XF, RR Evoque, Discovery, Discovery Sport with NLI Infotainment System
<p>Customer Voice:</p> <ul style="list-style-type: none">– Intermittent Bluetooth connection on Android equipped device with software 9.0 <p>Technical Description:</p> <ul style="list-style-type: none">– Under investigation with suppliers (Infotainment system & cellphone suppliers) <p>Status:</p> <ul style="list-style-type: none">– Reported on NLI vehicles pairing any Android device at 9.0 sw.– Please report all customer complaints via EPQR.	 <p>The image shows three smartphone screens. The leftmost screen is a lock screen with a purple and blue geometric pattern, displaying the time 12:45 and the date FRI, MARCH 14. The middle screen is a home screen with a large white number '8' on a light background, displaying the date Tuesday, Oct 9 and the temperature 68°F. The rightmost screen is a software information page with the following details: One UI version 1.0, Android version 9, Baseband version XN9AHLX1C52AG, Kernel version 4.9.0-1311-1400, Build number SPH1A60K1B017-030000HLX1C52AG, SE for Android status (not available), Knox version (Knox 2.21), and Service provider SW ver.</p>

