


# LATEST VEHICLE CONCERN FIXES



NLI – Bluetooth connectivity concerns with Android equipped device	15MY – 19MY E-Pace, F-PACE, F-TYPE, XE, XF, RR Evoque, Discovery, Discovery Sport with NLI Infotainment System
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>– Intermittent Bluetooth connection on Android equipped device with software 9.0</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>– Under investigation with suppliers (Infotainment system &amp; cellphone suppliers)</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>– Reported on NLI vehicles pairing any Android device at 9.0 sw.</li><li>– Please report all customer complaints via EPQR.</li></ul>	 <p>The image shows three smartphone screens. The leftmost screen is a lock screen with a purple and blue geometric pattern, displaying the time 12:45 and the date FRI, MARCH 11. The middle screen is a home screen with a large white number '8' on a light background, displaying the date Tuesday, Oct 9 and the temperature 68°F. The rightmost screen is the 'Software information' page, showing details such as One UI version, Android version, Baseband version, Kernel version, Build number, SE for Android status, Knox version, and Service provider SW ver.</p>

