

SERVICE ACTION H222 - ENGINE
MALFUNCTION INDICATOR LAMP (MIL)
ILLUMINATED

NAS19.06.013 | WORKSHOP

CAN/USA



AFTERSALES BULLETIN

JUNE 19, 2019

DESCRIPTION OF ISSUE

An issue has been identified on a limited number of Jaguar vehicles within the listed Affected Vehicle Range where the engine Malfunction Indicator Lamp (MIL) may incorrectly display on the Instrument Cluster with Diagnostic Trouble Code (DTC) P013E-00 stored in the Powertrain Control Module (PCM).

AFFECTED VEHICLE RANGE

F-PACE (X761; Ingenium I4 2.0L Petrol)

Model Year: 2018

VIN: 244395-283919

XE (X760; Ingenium I4 2.0L Petrol)

Model Year: 2018

VIN: P18447-P33269

XF (X260; Ingenium I4 2.0L Petrol)

Model Year: 2018

VIN: Y53994-Y64109

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer.

SERVICE PROGRAM / REWORK ACTION

Owners will be notified and instructed to take their vehicle to an authorized Jaguar retailer who will update the PCM software to the latest level. There will be no charge to owners for this action under this program.

OWNER NOTIFICATION

Owner notification is expected to occur on or before the week of July 22, 2019.

ACTION TO BE TAKEN

Use the Jaguar Land Rover claims submission system to make sure that the vehicle is affected by this Program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin H222NAS, *Service Action: Engine Malfunction Indicator Lamp (MIL) Illuminated*, for detailed repair instructions.

PARTS

No parts required.

TOOLS

Refer to the Technical Bulletin referenced above for any required special tools.

WARRANTY

NOTE: use the Jaguar Land Rover claims submission system to make sure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that all outstanding Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information listed have been included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Use TOPlx to obtain the latest repair time.

Warranty claims must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NUMBER	QUANTITY
H222	A	Powertrain Control Module (PCM) - Update - Replace ECU	85.18.03	0.2	-	-
H222	B	Powertrain Control Module (PCM) - Update - Replace ECU	85.18.03	0.2	-	-
		Drive in/drive out	10.10.10	0.2	-	-

Normal Warranty policies and procedures apply.

July 2019

Service Action H222: Engine Malfunction Indicator Lamp (MIL) Illuminated

**Vehicle Affected: Jaguar F-PACE, XE, and XF
Model Year: 2018**

Dear Jaguar Owner,

Jaguar Land Rover Canada ULC is conducting a no-charge Customer Satisfaction Program (Program Code H222) for owners of certain 2018 Model Year Jaguar F-PACE, XE, and XF vehicles.

What is the issue?

A potential quality issue has been identified where the engine Malfunction Indicator Lamp (MIL) may incorrectly display on the Instrument Cluster.

What will Jaguar and your Jaguar Retailer do?

An authorized Jaguar retailer will update the Powertrain Control Module (PCM) software to the latest level. There will be no charge to owners for this action under this program.

What should you do?

Contact your preferred authorized Jaguar retailer and provide them with your Vehicle Identification Number (VIN) and request a service date to complete the work required under Program Code **'H222'**.

During this visit, please take the opportunity to discuss any aspect of your vehicle's operation or performance with the Retailer team who will be pleased to assist you with any questions you may have regarding your vehicle in order for you to get the most out of its advanced features.

How long will it take?

The work will be carried out as quickly and efficiently as possible in order to minimize inconvenience to customers and is expected to take approximately 30 minutes, although your retailer may need your vehicle for a longer time. Your retailer can provide you with a better estimate of the overall time for the service visit.

Attention Leasing Agencies: please forward this notification to the lessee within 10 days.

Moved or no longer own this Jaguar vehicle?

If you are no longer the owner of this vehicle, Jaguar would greatly appreciate the name and address of the new owner, using the Information Change Form enclosed.

What should you do if you have further questions?

If you have any questions regarding this program or need assistance in locating the nearest authorized Jaguar retailer, please contact the Jaguar Canada Customer Relationship Center at 1-800-668-6257.

You may also contact us by email using the following address: jagcweb@jaguarlandrover.com. If you have the need to contact Jaguar by mail, please use the following address:

Jaguar Land Rover Canada ULC
75 Courtneypark Drive West, Unit 3
Mississauga, ON L5W 0E3

Thank you again for selecting Jaguar; your ownership experience is very important to us. We recognize this service visit may be an inconvenience to you. Jaguar, in cooperation with your authorized Jaguar retailer, will strive to minimize any inconvenience to you caused by this program.

Yours Sincerely,

A handwritten signature in black ink, appearing to read 'R Whisson', is positioned above the printed name.

Robert Whisson
Director, Customer Service
Jaguar Land Rover Canada ULC

Sample

July 2019

Service Action H222: Engine Malfunction Indicator Lamp (MIL) Illuminated

**Vehicle Affected: Jaguar F-PACE, XE, and XF
Model Year: 2018**

Dear Jaguar Owner,

Jaguar Land Rover North America, LLC is conducting a no-charge Customer Satisfaction Program (Program Code H222) for owners of certain 2018 Model Year Jaguar F-PACE, XE, and XF vehicles.

What is the issue?

A potential quality issue has been identified where the engine Malfunction Indicator Lamp (MIL) may incorrectly display on the Instrument Cluster.

What will Jaguar and your Jaguar Retailer do?

An authorized Jaguar retailer will update the Powertrain Control Module (PCM) software to the latest level. There will be no charge to owners for this action under this program.

What should you do?

Contact your preferred authorized Jaguar retailer and provide them with your Vehicle Identification Number (VIN) and request a service date to complete the work required under Program Code **'H222'**.

During this visit, please take the opportunity to discuss any aspect of your vehicle's operation or performance with the Retailer team who will be pleased to assist you with any questions you may have regarding your vehicle in order for you to get the most out of its advanced features.

How long will it take?

The work will be carried out as quickly and efficiently as possible in order to minimize inconvenience to customers and is expected to take approximately 30 minutes, although your retailer may need your vehicle for a longer time. Your retailer can provide you with a better estimate of the overall time for the service visit.

Attention Leasing Agencies: please forward this notification to the lessee within 10 days.

Moved or no longer own this Jaguar vehicle?

If you are no longer the owner of this vehicle, Jaguar would greatly appreciate the name and address of the new owner, using the Information Change Form enclosed.

What should you do if you have further questions?

Should you have any questions regarding this Program or need assistance in locating the nearest authorized Jaguar retailer, please contact the Jaguar Customer Relationship Center at 1-800-4JAGUAR (1-800-452-4827).

You may also contact us by email using the following address: jagweb1@jaguarlandrover.com. If you have the need to contact Jaguar by mail, please use the following address:

Jaguar Land Rover North America, LLC
ATTN: Customer Relationship Center
100 Jaguar Land Rover Way
Mahwah, NJ 07495

Thank you again for selecting Jaguar; your ownership experience is very important to us. We recognize this service visit may be an inconvenience to you. Jaguar, in cooperation with your authorized Jaguar retailer, will strive to minimize any inconvenience to you caused by this program.

Sincerely,

A handwritten signature in black ink, appearing to read 'Rory Beattie', written over a light blue horizontal line.

Rory Beattie
Vice President Customer Service
Jaguar Land Rover North America, LLC

Sample