


Latest Vehicle Concern Fixes



Restricted Performance & Judder (P0CE4- Drive Motor A)	19MY I-PACE
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customer may experience a “judder” with Restricted Performance message. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• P0CE4 for "Drive Motor A position exceeded learning limit" stored in both or either EPIC B or C. <p><u>Status:</u></p> <ul style="list-style-type: none">• Under Investigation• Follow TOPIx & Guided Diagnostics.• Raise a TA should additional support be required.• If a drive unit be replaced for this concern, please hold onto the part and raise an EPQR with your parts manager information.	 <p>The image shows a yellow warning triangle with an exclamation mark inside, set against a dark background. Below the triangle, the text "Restricted Performance" is displayed in white.</p>

