

Latest Vehicle Concern Fixes



Automatic Emergency Braking Not Available in Instrument Pack

Customer Voice:

- Automatic Emergency Braking not available
- Forward Alert not available
- Emergency Lane Keeping not available

Technical Description:

- Supplier manufacturing process error resulting in faulty hardware
- DTC set in IPMA "U3000-96 – Component Internal Failure"

Status:

- Supplier Permanent Corrective Action has been completed as of April 11th 2019
- Clean stock of parts
- Workshop Manual U3000-96 Help text will be altered to provide clear instructions to retailers
- Pathfinder logic is currently being reviewed to implement replacement of module if serial number falls in the criteria

18MY – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport

