


VOLVO CAR SERVICE AND PARTS BUSINESS				
<h1>Parts Bulletin</h1>				
TITLE: S29843: Fuel Filler Pipe Insert – Model Year 2017-2018 XC90 & V90 with T8 Engine; 2018 XC60 with T8 Engine				
GROUP: 23	CAT/NO: S29843	REFERENCE BULLETINS: QB S29843	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2017-09-14	STATUS DATE: 2017-09-14
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB S29843

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Action S29843 on certain model year 2017 - 2018 XC90, V90, and model year 2018 XC60 vehicles equipped with the T8 engine.

Volvo has identified that the fuel tank filler pipe insert was manufactured out of specification. This could result in malfunction indicator lamp (MIL) illuminated and a Driver Information Module (DIM) message “check engine.”

The corrective action is replacement of the filler pipe insert per the VIDA instructions located per the VIDA path below.

Information → Repair → Removal, Replacement and Instructions → 2 Engine With Mountings and Equipment → 23 Fuel Systems → Fuel Tank, Fuel Lines, Evaporator System → Fuel Tank Filler Pipe Nozzle

Service Action S29843 affects 868 vehicles in the U.S. and 137 in Canada.

The following part number applies:

Part Number	Description	Qty
32203722	Insert	1