



Technical Service Bulletin

Technical Service Bulletin: TSB190115	Released Date: 02-Jul-2019
Navistar® Dashboard Odometer Discrepancy	

Navistar® Dashboard Odometer Discrepancy

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- Engine:
 - B6.7 B121B CM2350
 - ISB B101 CM2350
 - ISL L101 CM2350
 - ISX X101 CM2350
 - L9 L116B CM2350
 - X15 X114B CM2350
 - X15 X116B CM2350
- Original equipment manufacturer (OEM)
 - Navistar™

Issue

Symptom:

- Navistar truck dashboard odometer can show incorrect value under certain conditions. When electronic control module (ECM) is replaced or the ECM is ROM booted.

Root Cause:

- Navistar™ algorithm is adding the existing odometer reading to the odometer value during key start after an ECM is replaced or ROM booted, doubling truck mileage on the dashboard odometer.

Verification

- Truck dashboard odometer displays incorrect mileage.

Service Instructions

- Contact nearest Navistar® Certified Dealer.
 - Diamond Logic Builder tool will change the value of the dashboard odometer whenever a customer experiences this issue.

Document History

Date	Details
2019-6-27	Module Created

Last Modified: 02-Jul-2019
