

Latest Vehicle Concern Fixes



17 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System

Pop Noise from Audio Output

Customer Voice:

- Popping sound or crackling noise from the audio system while in use.

Technical Description:

- Under investigation, could be IMC or AAM software

Status:

- Primarily reported on Range Rover Velar or Land Rover Discovery
- Please submit a TA case with primary and secondary diagnosis with video recording of the information below:
 - 1 kHz sine wave test from a usb stick
 - 1 kHz sine wave test from a Bluetooth audio source
 - Play classical music or talk show radio from FM / AM source
 - Play classical music or talk show radio from Satellite radio source

