

Solution K31740044 Friday, July 26, 2019 7:00:35 PM CEST

** SOLUTION **

Title	Volvo Chassis - FSB 375 - 013 - Bluetooth Radio And Handsfree Phone Audio, Repair
Volvo Models	
Volvo Model	VNL, VNM, VNR, VNX, VAH, VHD
** SOLUTION **	
Cause	On certain Volvo models with Bluetooth radio and LDWS (Lane Departure Warning System); the audio for the Bluetooth phone call may be low and with poor quality.
Solution	Please refer to <u>eMedia Center</u> for information regarding FSB375 - 013.
Solution visibility	Dealer distribution
Function(s)/compone	ent(s) affected
Function affected	Diagnostic tool, FSB
Function Group	
Function Group	392 radio, complete , 393 equipment for entertainment , 395 radio, entertainment and communication , 881 instrument and radio panel
Customer effect	
Main customer effect	fault code/display
Fault Codes And Erro	
US10 Fault Codes (SPN-FMI Format)	SPN 1703 FMI 5 , SPN 1704 FMI 5
Administration	
Author	A241298
Dealer ID	A241298
Last modified by	A241298
Creation date	08-07-2019 17:07
Date of last update	08-07-2019 18:07
Status	Published