
Reference	SSM74446
Models	Discovery / L462 Discovery Sport / L550 Range Rover Evoque / L538
Title	Bluetooth connectivity using Android operating system devices
Category	Electrical
Last modified	07-Jun-2019 00:00:00
Symptom	207000 Entertainment Systems
Content	<p>Issue: Inconsistent Bluetooth connectivity for Android based operating systems following an Android software update to PIE 9. The concern will only affect New Low line Infotainment (NLI) systems.</p> <p>Cause: Software compatibility issue.</p> <p>Action: Land Rover are currently developing a solution and will publish the required service procedure on TOPIx in the near future. In the meantime please do not replace any components or carry out diagnosis in an attempt to rectify the concern.</p>