Latest Vehicle Concern Fixes





Heavier Then Expected Steering

Customer Voice:

• Customer states the steering is heavier than expected.

Technical Description:

• The sleeve on I-shaft may have moved down on the I-shaft.

Status:

- LTB01224 is on sign-off to replace the bulk head seal and I-shaft when parts are available.
- ETA on new I-shaft is the 20th of June

2016 Onwards Range Rover & Range **Rover Sport**













