



Technical Service Bulletin

Technical Service Bulletin: TSB140026	Released Date: 20-Aug-2019
New Exhaust Manifold Gasket	

New Exhaust Manifold Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISL9 CM2350 L101
 - Application: North America Transit Bus **Only**
- L9 CM2350 L123B
 - Application: North America Transit Bus **Only**
- ISL G CM2108

Description of Change

This document introduces new part numbers for the exhaust manifold gasket.

Reason for Change

New exhaust manifold gasket and exhaust manifold section, Part Number 5321189, reduces warping and improves sealing at high operating temperatures.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
GASKET,EXH AUST MANIFOLD	5269779	No	No	5316185

Part Identification



Document History

Date	Details
2014-2-25	Module Created
2014-3-12	none
2019-8-16	Updated project affected and added Figure 1.

Last Modified: 20-Aug-2019
