

Technical Service Bulletin

SUBJECT:			No:	TSB-19-52A-003
CORRECTION TO FRONT PILLAR TRIM			DATE:	August 2019
ASSEMBLY INSTALLATION PROCEDURE - SMR				2015-19 Outlander Sport/RVR
CIRCULATE TO:	[] GENERAL MANAGER	[] PARTS MANAGER		[X] TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCESSOR		[] SALES MANAGER

PURPOSE

This TSB updates the Interior and Supplemental Restraint System (SRS) section of the affected Service Manuals, to correct the front pillar trim assembly installation procedure.

AFFECTED VEHICLES


• 2015 - 2019 Outlander Sport/RVR

AFFECTED SERVICE MANUAL


 2015 - 2019 Outlander Sport/RVR Service Manual, Group 52-Interior and Supplemental Restraint System (SRS)




Please make the indicated changes to the 2015 Outlander Sport/RVR Service Manual, Group 52-Interior and Supplemental Restraint System (SRS) -> Group 52A-Interior -> Trims -> Interior Trim Removal and Installation.



Please make the indicated changes to the 2016 Outlander Sport/RVR Service Manual, Group 52-Interior and Supplemental Restraint System (SRS) -> Group 52A-Interior -> Trims -> Interior Trim Removal and Installation.



Please make the indicated changes to the 2017 Outlander Sport/RVR Service Manual, Group 52-Interior and Supplemental Restraint System (SRS) -> Group 52A-Interior -> Trims -> Interior Trim Removal and Installation.



Please make the indicated changes to the 2018 - 2019 Outlander Sport/RVR Service Manuals, Group 52-Interior and Supplemental Restraint System (SRS) -> Group 52A-Interior -> Trims -> Interior Trim Removal and Installation.

