


## Latest Vehicle Concern Fixes



Restricted Performance & Judder (P0BEx- Drive Motor A)	19MY I-PACE
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• Customer experiences judder with Restricted Performance message.</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• Variations of P0BE5, P0BE9, P0BED or "Drive Motor A Phase U, V, or W current sensor" are stored in either EPIC B or C.</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• Under Investigation</li><li>• Follow Pathfinder Guided Diagnostics &amp; TOPIx workflow.</li><li>• Raise a TA should you need additional support. If a drive unit or an EPIC is replaced for this instance, please raise an EPQR with your parts manager information.</li></ul>	 <p>The image shows a yellow warning triangle with an exclamation mark inside, set against a dark background. Below the triangle, the text "Restricted Performance" is displayed in white.</p>

