


Latest Vehicle Concern Fixes



A-Pillar Water Ingress	XF Sportbrake 18 – 19MY
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• A customer may express a concern of water leaking into the driver's footwell. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• This may be caused by a manufacturing error with the robotic sealing process. <p><u>Status:</u></p> <ul style="list-style-type: none">• TSB JTB00694NAS1 is being published to provide diagnosis guidance for the source of the water leak, along with repair instructions should a leak be found from the body seam.• Should a customer express a concern, please refer to the TSB.	 <p>E246392</p>

