

Latest Vehicle Concern Fixes



Cell Module Imbalance	19 & 20MY I-PACE
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customer may experience various warnings & symptoms i.e. difficulties charging the vehicle, a Traction Battery Warning, or inability to start the vehicle, Reduced Performance Warning. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• Various codes for Hybrid/EV Battery Cell Module XX- Signal failure. <p><u>Status:</u></p> <ul style="list-style-type: none">• Run 40D2 test in the BECM. BECM ECU Function- HV Hot Spot Cell Module Data• Results do not populate easily in the session file, take screen shots of the 40D2 test• 40D2 Test will ask technicians to charge the vehicle for 10 minutes. The test will still run if you are unable to charge the vehicle• Prior to case submission, please have you designated EVSAP pressure the HV Battery	

