

Measure no.

US 64678027-03

Subject

Seat is difficult to close - seats available

Status date (mm/dd/yy)

5/29/19

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

5/29/19

Created by

Michael Gersbach

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K08 K09

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

Seat catch (striker) fits improperly in the seat lock

Cause

The tolerance between the catch and seat is too tight.

Measure

Seat catch (striker) fits improperly in the seat lock

The tolerance between the catch and seat is too tight

The seat has been optimized so that the catch (striker) fits appropriately in the seat lock.

The optimized seats are now available and can be ordered under the existing part numbers.

Complaint**Fault location**

51/25 Seat lock

Fault typeCannot be encoded with
VFC**Fault place**

Cause

| # | Fault location | Fault type | Fault place |
|---|-----------------------------------|--------------------------|---------------|
| 1 | 51/25 Seat lock | | |
| | Repair Task | Special Clearance | Area |
| | Checking, repairing, replacing | No | Body and Trim |

Fault code

Progman / DIS / ISTA / ISTA/P

| System | State | Version |
|--------|-------|---------|
|--------|-------|---------|
