



Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf	2016-2019	All	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2052659/3	9/19/19	60-18-02TT	Updated to add felt strip length.
2052659/1	10/12/18	TT 60-18-02	Original publication.

Technical Background

The Detents for retaining the Sunshade can become weak leading to the Sunshade opening slightly while driving.

Service

- Carefully remove approximately 2mm of material from the rear section of the Rubber Bump Stop (Figure 1).
- Apply a 1 inch to 2 inch (25mm-50mm) strip of Felt Tape to the Track by the End Stop (Figure 2). Felt Tape part number 533 863 288 A from the VAS Noise Elimination Kit can be used.



Figure 1



Figure 2



60-18-02TT Manual Sun Shade Will Not Stay Closed or Opens Slightly While Driving

Release date: 09/20/2019

Additional Information

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.