

** SOLUTION **

	Diagnostic Trouble Code (DTC) P229F-64; Diagnostic Information - US10+OBD2013 Emissions And Newer	
Mack Models		
Mack Model	LEU, LR, MRU - TerraPro, TE - TerraPro, AN - Anthem, CHU - Pinnacle, Axle back, CXU - Pinnacle, Axle front, GR - Granite, GU - Granite, PI - Pinnacle, TD - Titan	
Volvo Models		
Volvo Model	VN, VNL, VNM, VNR, VNX, VAH, VHD, VT	
Emission Standard		
Emission Standard	US10+OBD13, US14, US14+OBD13, US14+OBD15, US14+OBD16, US17, US 17+OBD16, US17+OBD18, US17+OBD19	
Engine family		
Engine family	11L Engine, 13L Engine, 16L Engine, MP7, MP8, MP10	
** SOLUTION **		
Cause	The fault code P229F-64 is evaluating the SCR outlet NOx l is expected to be higher than 10 parts per milloin (ppm). Or excellent condition, the actual SCR outlet NOx level can be time, including times when an aged EATS muffler is expect NOx, an expected change from normal use. Getting this cod	n a new EATS muffler in close to zero most of the ed to have more than 10 ppn
	indication of NOx sensor failure or EATS system failure.	
Solution	If a vehicle has this code logged on a DTC Readout: - Review the Detailed Status Information for the relevant code	e on the DTC Readout.
Solution	If a vehicle has this code logged on a DTC Readout: - Review the Detailed Status Information for the relevant code	e on the DTC Readout.

• If Confirmed DTC is **FALSE**: Do not troubleshoot the code.

Function affected	SCR
Customer effect	
Main customer effect	fault code/display
Fault Codes And Erro	or Codes
OBDII Diagnostic Trouble Codes (P, U, B Format)	P229F
Administration	
Author	UT0031H
Dealer ID	UT0031H
Last modified by	A241298
Creation date	30-05-2019 21:05
Date of last update	26-09-2019 20:09
Review date	31-05-2020 00:05
Status	Published
NA_Reviewer	ut0031h
NA_Author_Group	GTT

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.