

Subject

Abnormal Noise from Front Over Bumps and/or During Turns

Market

USA

Service Category

Suspension

Section

Front Suspension

Applicability

2019 Corolla

APPLICABLE VEHICLES

2019

Corolla

CONDITION

Some 2019 model year Corolla vehicles may experience an abnormal noise from the front over bumps and/or during turns from the front lower control arm bushing, both left and/or right sides.

RECOMMENDATIONS

This condition is currently under investigation. Confirm the condition by applying water to the bushing area. **DO NOT USE SILICONE OR GREASE.**

If the noise **DOES** change, please contact Technical Assistance (TAS) to submit details on any vehicles with the condition and to obtain further direction.

If the noise **DOES NOT** change, continue diagnosis using the applicable repair manual section.

If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available work day.

LINK REFERENCES

This Tech Tip does not contain any link references