



<b>Countries:</b>	AUSTRALIA, BRAZIL, CANADA, UNITED STATES, SOUTH AFRICA	<b>Document ID:</b>	IK0500007
<b>Availability:</b>	ISIS, Bus ISIS, FleetISIS	<b>Revision:</b>	4
<b>Major System:</b>	STEERING SYSTEM	<b>Created:</b>	12/21/2006
<b>Current Language:</b>	English	<b>Last Modified:</b>	8/16/2013
<b>Other Languages:</b>	<a href="#">Français</a> , <a href="#">Español</a> ,	<b>Author:</b>	Anthony Kelso
<b>Viewed:</b>	722		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 <a href="#">View My Bookmarks</a>				 115	 265

**Title: Adjustment Procedure for Tilt Only Steering Column Feature 0005708**

**Applies To: Model: CE200 BE200 CE300 3200 3300 ,DuraStar, WorkStar, TransStar, Prostar "Deluxe", TerraStar, AE Bus, AC Bus**

**DESCRIPTION**

The information supplied herein has been furnished by the manufacturer and/or the supplier for use with its product. International Truck and Engine Corporation reprints this information based on representations made to the Company. While users are urged to carefully follow the instructions accompanying the product, International cannot accept any responsibility for user errors, or mishaps resulting from such errors, or from any misuse of the product. Refer to the [pdf for this article](#) for the Autotec Service Bulletin for more information.

TSI Number: 04-05-01 Tilt Steering Column Adjustment

Hide Details

Feedback Information

Viewed: 721
Helpful: 115
Not Helpful: 265
No Feedback Found