



Countries: CANADA, UNITED STATES
Document ID: IK2200018
Availability: ISIS, FleetISIS
Revision: 5
Major System: BUS BODY
Created: 1/14/2007
Current Language: English
Last Modified: 8/9/2013
Other Languages: [Français](#), [Español](#),
Author: Bob Ford
Viewed: 392

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 65	Not Helpful 37
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	------------------------------

Title: Reinforcement of the Battery Box CE RE FE and BE Buses

Applies To: Model: Bus Start Date: 03/09/1999 End Date: 12/12/2006

DESCRIPTION

On some bus models the bottom of the battery box may deform, or begin to separate from the sides of the box under the weight of the vehicle's batteries. A field kit that contains two corner supports and fasteners, for reinforcement of the battery box is now available to address this issue.



Before Repair




After Repair

PARTS INFORMATION

Part No.	Description	Quantity
2592799C91	Battery Box Reinforcement Kit	
	Contents:	
2592800C1	Instruction Sheet, Battery Box Reinforcement Kit	1

2592801C1	Support, Reinforcement Angle (Figure 2)	2
424329001	Rivet, 1/4 Huck Magna Bulb (Figure 3)	16



Side

Bottom

Brackets in kit

Click here for complete installation instructions **TSI Number:** [07-47-01R](#)

Hide Details

Feedback Information

Viewed: 391
 Helpful: 65
 Not Helpful: 37

No Feedback Found