

### **Tech Tip** T-TT-0572-19

September 10, 2019

# DTC B15A8 - DCM System Internal Failure

USA

Audio/Visual/Telematics

Cellular Communication

All Applicable Models

## **APPLICABLE VEHICLES**

2020	Camry	2020	Corolla Hatchback
2020	Camry HV		

#### **CONDITION**

Some 2020 model year Camry, Camry HV and Corolla Hatchback vehicles equipped with a DCM may exhibit a B15A8\*\* DTC in history during PDS. This DTC can be triggered during the manufacturing and /or shipping process and does not indicate a problem with the vehicle. To simplify the diagnosis of this DTC, refer to the procedure below to prevent unnecessary parts replacement.

## **RECOMMENDATIONS**

Is the DTC current or a history DTC?

- Current Continue diagnosis via the appropriate Repair Manual.
- History Clear the DTC

#### **LINK REFERENCES**

This Tech Tip does not contain any link references