



Preliminary Information

PIC6372 Pre-Screened MSDs (Manual Service Disconnect) To Be Acquired Through WPC

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Bolt EV	2017 - 2020	All	All	All	All

Involved Region or Country	North America
Condition	The Bolt EV Manual Service Disconnect Lever (with fuse) has been placed into the Temporary Service Part process to ensure service part quality.
Cause	A quality issue has been identified with the MSD fuse. The fuse and lever is serviced as an assembly.

Correction:

Parts are being qualified by the supplier.

The MSDs can be obtained from the Warranty Parts Center (WPC) using the TSP Dealer Request Form

This form is located on:

Global Connect<Service Department<Service Forms Application<General Information tab<TSP Dealer Request Form.

Instructions for submitting are on the form.

Request WPC842.



New part must have:

1) The Blue V means it passed resistance Measurements

2) Black dot means it completed thermo cycle 9 times.

Version History

Version	1
Modified	10/29/19 - Created on.



© 2019 General Motors. All Rights Reserved.