

Subject: Engineering Information – Charge Port Receptacle Melting On the Vehicle

This EI has been revised to end the need for information from the field. Please discard PIE0535.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EV	2017	2020	-	-	-	-

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 22, 2019 October 30, 2019 – Ended the need for further information from the field.